

T. 39 S. R. 11 E. W. M.

Sec. 5

S 57° 09' E.

← To Dairy

To Bonanza →

1 1/2 Miles

Jonah Sparks
103-520

Jonah Sparks

Hauling Road
50 wide

1/4 Con. →

60' County Road

Lease No. Q 482
Expires Mar. 1956

Area 6.51 A.
Quarry
West 630'
East 630'
South 450'
North 450'

T. 39 S., R. 11 E.

8

OREGON STATE HIGHWAY DEPARTMENT-	
LEASED FROM	Jonah Sparks
For	Rock Quarry and Hauling Road Easement
Highway	Dairy - Bonanza
County	KLAMATH.
Scale 1" = 400'	Date March 1936.